

ISO 9001 : 2015 & MSME Certified Laboratory

## TEST REPORT

Name & Contact Information of the Customer:

SIDDHI RUBBER UDYOG
PLOT NO. C-127, SECTOR 10, NOIDA-201301

(U.P.) INDIA

Report No.: B202303150001

Issue Date: 15/03/2023

Test Duration: 11/03/2023 to 15/03/2023

Date of Receipt: 11/03/2023

Sample Quantity:2 pcs
Sample Condition: OK

Ref. No. & Date: NIL , dt. 11/03/2023

Page No.: 1 of 1

Sample Description: Geo Composite Double Side

S.No	DESCRIPTION	UNIT	VALUE	STANDARD
L	Static puncture resistance	N	2150	EN ISO 12236 : 2006
2.	Tensile strength MD	kN/m	22	EN ISO 10319 : 2008
3.	Strain at max load MD	%	55%	EN ISO 10319 : 2008
4.	Tensile strength CMD	kN/m	27.2	EN ISO 10319 : 2008
5.	Apparent opening size	1/(m.s)	1 to 3	EN ISO 12958 : 2010
6.	Permeability	m/s	2.5*10/3	A STATE OF THE STA
7.	gradient i = Type of conduct	S/S - -	1.0 R/R 0.682 0.645 0.561	
8.	Thickness .mm		6 - 4	ASTM D: 5199 : 2012
9.	Mass per unit area g/m2	a many alle	730	ASTM D: 5219 : 2010

\*\*\*END OF REPORT\*\*\*



## **BHUMI TEST HOUSE**

109/7, Phimi Road, Mundka, New Delhi-110041, T.: 9910541479, 8376926426
E.: a2btllab@gmail.com, bth0422@gmail.com | info@bhumitesthouse.in account@bhumitesthouse.in | W.: www.bhumitesthouse.in

(1) The above result are related only to the test performed on the sample. Endorsement of product is neither inferred nor implied.
 (2) This report is not to be reproduced wholly or in part forbidden to be used as an evidence in the court of law & ought not to be used in any advertising media without our special permission in writing.
 (3) Sample will be destroyed after 15 & 30 days from the date of reporting unless otherwise specified.
 (4) Total liability of our test house is limited to the invoiced amount.
 (5) Report refers to the sample received by us.